Falls Church South Washington Street TLC Study
Long-Term Recommendation

Note: If South Maple Avenue is closed at South Washington Street, the stoplight and crosswalk proposed for the intersection would be removed (or not installed). Additionally, the recommendation for a hybrid signal and marked crosswalk proposed for the South Washington Street crossing near Tinner Hill Road would be replaced by a recommendation for a full stop light and cross walk on all four legs of the Tinner Hill Road/South Washington Street intersection.